

— THE VILLAGE OF —
SWANTON

May 29, 2019

300 South Street
Swanton, Ohio 43558
T: 419.826.5891
F: 419.825.1827
www.villageofswantonohio.us

During our CSO monitoring inspection, this morning, Village WRRF staff found CSO discharges at the following locations:

CSO #019 N Main St.
CSO #024 Brookside @ Crestwood St.
CSO #028 Hallett @ Zeiter Way

NPDES Permit # 2PB00025
Receiving water: AI Creek
Public access areas: AI Creek
Date: May 29, 2019

Time we became aware of #019 discharge: 0853 hours
Time discharge ended: 0853 hours Discharge not active
Time we became aware of #024 discharge: 0900 hours
Time discharge ended: 0900 hours Discharge not active
Time we became aware of #028 discharge: 0906 hours
Time discharge ended: 0906 hours Discharge not active

Cumulative volume of the CSO discharges: 24000 gallons

Point of contact: Rosanna Hoelzle, Village Administrator



WATER RESOURCE
RECOVERY FACILITY
SUPERINTENDENT

Steve Geise

Sincerely,

Steve Geise
Superintendent
Swanton WRRF