

— THE VILLAGE OF —
SWANTON

August 19, 2019

300 South Street
Swanton, Ohio 43558
T: 419.826.5891
F: 419.825.1827
www.villageofswantonohio.us

During our CSO monitoring inspection, today, Village WRRF staff found CSO discharges at the following locations:

CSO #024 Brookside @ Crestwood St.
CSO #027 Church St.
CSO # 028 Hallett @ Zeiter Way

NPDES Permit # 2PB00025

Receiving water: AI Creek

Public access areas: AI Creek

Date: August 19, 2019

Time we became aware of the CSO #024 discharge: 1005 hours

Time discharge ended: 1005 hours

Discharge not active

Time we became aware of the CSO #027 discharge: 1310 hours

Time discharge ended: 1310 hours

Discharge not active

Time we became aware of the CSO #028 discharge: 1013 hours

Time discharge ended: 1013 hours

Discharge not active

Cumulative volume of the CSO discharges: 16,100 gallons

Point of contact: Rosanna Hoelzle, Village Administrator



WATER RESOURCE
RECOVERY FACILITY
SUPERINTENDENT

Steve Geise

Sincerely,

Steve Geise
Superintendent
Swanton WRRF